

This Page Is Inserted by IFW Operations  
and is not a part of the Official Record

## **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

**IMAGES ARE BEST AVAILABLE COPY.**

**As rescanning documents *will not* correct images,  
please do not report the images to the  
Image Problem Mailbox.**





Fig. 1

Fig 2






Fig. 3



MODULE WITH POP-OUT OUTLETS




ELECTRICAL  
SCHEMATIC  
FIG. 5



NOTE: A 3 MOV SURGE  
PROT. BD. REQUIRES  
THE PARTS C1, F2  
F3, M1, M7, & M8

MODULE  
WITH POP-OUT  
OUTLETS

EXTENDED  
POP-OUT  
OUTLETS  
(4 OUTLETS  
PER POP-OUT)



DIAGRAMATIC  
VIEW  
FIG. 4






Fig. 7




FIGURE 7A




Fig. 8






Fig. 9







Fig. 10






FIGURE 14